ZR-6 Software Package v2.01



IMPORTANT—PLEASE READ THE ENTIRE DOCUMENT BEFORE DOWNLOADING

Feature summary for this software release:

- Five legacy sources may now be used when an iPod is not connected.
- IR mapping discrepancies on the TS-Pro touch screen have been resolved
- DC output protection on the ZR-6 has been improved.

See Release Notes Section 3.0 for more details.

1.0 OVERVIEW

- 1.1 File Name: setup zr6 v201.exe
- 1.2 Version: 2.01
- 1.3 Date Published: 28 September 2009
- 1.4 Language: English
- 1.5 Download Size: 30MB
- 1.6 Estimated Download Time: Approximately 60 minutes @ 56K; approximately 6 minutes @ DSL/Cable speeds
- 1.7 The ZR-6 Software Package 2.01 download contains:

 ZR-6 Utility Software 	v2.41
 ZR-6 Chassis Firmware 	v3.26
 TS-Pro Touchscreen Firmware 	v0.67
 Solo-6MD Keypad Firmware 	v2.07
Solo-6IR Keypad Firmware	v2.02
Read Me File	v2.01c
Help File	v2.01c
Troubleshooting File	v2.01c

NOTE: All devices in the system must be updated to the versions listed above to ensure proper operation.

IMPORTANT NOTE Prior to updating the ZR-6's firmware, it is recommended that you DOCUMENT (WRITE DOWN) ANY EXISTING CONFIGURATION DATA (I.E., SOURCE NAMES, TUNER PRESETS, ZONE LINKING, PAGING, ETC.) previously programmed in the ZR-6 chassis. See section 5.1 for more details.

2.0 SYSTEM REQUIREMENTS

- 2.1 Supported Operating Systems: Microsoft Windows® XP (Home and Professional) and Windows Vista® (32-bit)
- 2.2 Required Software: Microsoft[®]. Net Framework 2.0 or later (installer software will install .Net Framework 2.0 if not found).
- 2.3 Disk Space Required: 30MB
- 2.4 RAM Required: 512MB
- 2.5 COM Port: Serial Port or USB (Requires USB to Serial (DB-9) Adapter, see section 5.3 for more details)

3.0 RELEASE NOTES

3.1 The following outlines key enhancements in ZR-6 Package v2.01

3.1.1 ZR-6 Chassis Firmware v3.26

- 3.1.1.1 Improves monitoring and protection against DC output to speakers
- 3.1.1.2 Resolves IR code mapping discrepancies

3.1.2 ZR-6 Utility Software v2.41

3.1.2.1 Improves communication with ZR-6 and user interfaces

3.1.3 Solo-6IR Firmware v2.02

3.1.3.1 Improves ZR-6 communication when using a ZR-KE with a TS-Pro Touchscreen

3.1.4 Solo-6MD Firmware v2.07

- 3.1.4.1 Enables use of 5 legacy sources in a single system
- 3.1.4.2 Resolves issue where numeric screen (123...) was not accessible on some devices

3.1.5 TS-Pro Firmware v0.67

- 3.1.5.1 Enables use of 5 legacy sources in a single system
- 3.1.5.2 Resolves IR code mapping discrepancies
- 3.1.5.3 Resolves timer conflicts with custom images and menus

4.0 INSTRUCTIONS

- 4.1 Click the Download button on this page to start the download
 - 4.1.1 Do one of the following:
 - 4.1.1.1 To save the download to your computer, click **Save**.
 - 4.1.1.2 To cancel the installation, click **Cancel**.
 - 4.1.2 After successfully installing the program, an icon will appear on your desktop. Double-click this icon to launch the application.

5.0 IMPORTANT. READ THE FOLLOWING INSTALLATION CONSIDERATIONS CAREFULLY.

5.1 Document Existing Configuration Data Prior to Updating Firmware

5.1.1 Prior to updating the ZR-6's firmware, we recommend you DOCUMENT (WRITE DOWN) ANY EXISTING CONFIGURATION DATA (I.E., SOURCE NAMES, TUNER PRESETS, ZONE LINKING, PAGING, ETC.) previously programmed into the ZR-6 chassis.

NOTE: It is recommended that within the ZR-6 Utility Software you save (all) configuration data prior to updating the firmware.

5.2 Microsoft .Net Framework 2.0 or later must be installed

5.2.1 Microsoft .Net Framework 2.0 or later must be actively installed on your computer in order to install ZR-6 Utility Software. If not found, the installation software will install it. NOTE: Later versions of .Net Framework require significantly more disk space and download time.

5.3 Compatible USB to Serial (DB-9) Adapters

5.3.1 If your computer is not equipped with a Serial (DB-9) connecter, it is highly recommended that you use one of the following USB to Serial (DB-9) adapters that have been tested by Niles.

IMPORTANT A USB to Serial (DB-9) adapter is a "device" and requires that its respective driver be properly installed on your computer. Follow the manufacturer's instructions for installation.

- 5.3.1.1.1 Dynex, Model# DX-UBDB9
 - Best Buy SKU#: 7135664
- 5.3.1.1.2 Gigaware, Model# 26-949
 - Radio Shack SKU#: 26-949
- 5.3.1.1.3 IOGear, Model# G-UC232A
 - Tiger Direct SKU#: A225-1031
 - Amazon SKU#: GUC232A
- 5.3.1.1.4 USB to Serial Adapters utilizing Prolific[®] chipsets have been tested

NOTE: For added convenience, you can utilize a Male-to-Female, DB-9-to-DB-9 extension cable. This cable must be a pin-to-pin, straight-through cable.

6.0 TROUBLESHOOTING

6.1 Please review sections 2.0 and 5.0 and make any necessary adjustments

6.2 USB to Serial (DB-9) adapter Not Found or Error message

- 6.2.1 If the USB to Serial (DB-9) Adapter cannot be found or you encounter an error message, please retry the USB adapter in the computer's next available USB port. Continue trying different ports until the computer recognizes the USB adapter. Microsoft Windows will launch a window titled "Add Hardware Wizard" when it recognizes the USB adapter. Then, follow the instructions in the Wizard. NOTE: The USB adapter should be plugged directly into the computer and not indirectly through a hub or docking station.
- 6.2.2 If the USB to DB-9 Adapter still cannot be found or you encounter an error message, please do the following:
 - 6.2.2.1 For Windows XP and Windows Vista operating systems do the following:
 - 6.2.2.1.1 Navigate to **Control Panel** and select **System**
 - 6.2.2.1.2 In the Systems Properties window select **Hardware**
 - 6.2.2.1.3 Under the Hardware Tab select **Device Manager**
 - 6.2.2.1.4 In the Device Manager select **Ports**. If you see a yellow "question mark" or red "X" you have a conflict in your ports or USB section. The conflict(s) must be resolved to proceed with installation.

6.3 Not Able to Communicate with ZR-6

- 6.3.1 If you are having problems establishing communication with the ZR-6, and you've confirmed that the USB port functions properly, please do the following.
 - 6.3.1.1 Power Off the ZR-6, wait 5 seconds, then Power On the ZR-6. Wait until a tuner station appears in the LCD display to ensure that the ZR-6 initializes completely before proceeding. If the unit is still not communicating, proceed to the next step.
 - 6.3.1.2 Click the Advanced button. Select each COM port manually in the COM Port selection drop down list. IMPORTANT: Before each attempt, Power Off the ZR-6, wait 5 seconds, then Power On the ZR-6. Wait until a tuner station appears in the LCD display to ensure that the ZR-6 initializes completely before proceeding.
 - 6.3.1.3 If there are several COM ports displayed you may be able to narrow down which COM port is assigned to the USB adapter by navigating to **Device Manager** and reviewing COM port list.
- 6.3.2 If you still cannot communicate with the ZR-6 chassis, you may need to adjust the buffer size on the COM Port being utilized to perform the firmware update. IMPORTANT: After adjusting the setting, Power Off the ZR-6, wait 5 seconds, then Power On the ZR-6. Wait at least 10 seconds after Power On to ensure that the ZR-6 initializes completely before proceeding.
 - 6.3.2.1 For Windows XP operating systems do the following:
 - 6.3.2.1.1 Navigate to **Control Panel** and select **System**
 - 6.3.2.1.2 In the Systems Properties window select Hardware
 - 6.3.2.1.3 Under the Hardware Tab select **Device Manager**
 - 6.3.2.1.4 In the Device Manager select **Ports** and double-click on the port that is being used for the firmware update
 - 6.3.2.1.5 In the Communications Port Properties window select **Port Settings**
 - 6.3.2.1.6 Under the Port Settings tab select **Advanced**
 - 6.3.2.1.7 Under Advanced Settings locate the "Buffer Size" section
 - 6.3.2.1.8 Set the buffer size adjustment to the **Lowest** setting
 - 6.3.2.1.9 If necessary, follow additional instructions provided by USB adapter manufacturer for correcting performance and response problems.
 - 6.3.2.2 For Windows Vista operating systems do the following:
 - 6.3.2.2.1 Navigate to Control Panel and select System & Maintenance
 - 6.3.2.2.2 In the Systems & Maintenance page select System
 - 6.3.2.2.3 In the System page select **Device Manager**
 - 6.3.2.2.4 In the Device Manager select **Ports** and double-click on the port that is being used for the firmware update
 - 6.3.2.2.5 In the Communications Port Properties window select **Port Settings**
 - 6.3.2.2.6 Under the Port Settings tab select Advanced
 - 6.3.2.2.7 Under Advanced Settings locate the "Buffer Size" section
 - 6.3.2.2.8 Set the buffer size adjustment to the **Lowest** setting

6.3.2.2.9 If necessary, follow additional instructions provided by USB adapter manufacturer for correcting performance and response problems

6.4 COM Port Not Available or is Being Used By Another Application

- 6.4.1 If you are having problems establishing communication with the ZR-6, and you've confirmed that the USB port is functioning properly, please do the following.
 - 6.4.1.1 Click the Advanced button. Select each COM port manually in the COM Port selection drop down list. IMPORTANT: Before each attempt, Power Off the ZR-6, wait 5 seconds, then Power On the ZR-6. Wait until a tuner station appears in the LCD display to ensure that the ZR-6 initializes completely before proceeding.
 - 6.4.1.2 If there are several COM ports displayed you may be able to narrow down which COM port is assigned to the USB adapter by navigating to **Device Manager** and reviewing COM port list.

7.0 TECHNICAL SUPPORT

7.1 Should you have additional questions you can contact Niles Technical Support at 1-800-289-4434 or 1-305-238-4373 between the hours of 8:00 a.m. and 7:00 p.m. Eastern Time, Monday through Friday. Niles Technical Support can be reached via e-mail at <u>support@nilesaudio.com</u>.

Niles Audio Corporation 12331 S.W. 130 Street Miami, FL 33186 www.nilesaudio.com

©2009 Niles Audio Corporation. All rights Reserved. Niles and the Niles logo are registered trademarks of Niles Audio Corporation. All other trademarks are the property of their respective owners.9/29/09